Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 801-538-7223 (TDD)

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

INSPECTION REPORT

Partial: <u>X</u>	_ Complete:	Exploration:
Inspection Date & Time:	07/27/2000 8:30 A	.M. to 10:30 A.M
•	Date of Last Inspe	

Mine Name: Bear Canyon Mine	County: Em	ery	Permit Number	: ACT/015/025		
Permittee and/or Operator's Name: Co-	Op Mining (Company				
Business Address: P.O. Box 1245, Huntington, Utah 84528						
Type of Mining Activity: Underground	i <u>XXX</u> S	urface	Prep. Plant	Other		
Company Official(s): Charles Reynolds	3			· .		
State Officials(s): Robert Davidson						
Federal Official(s):						
Weather Conditions: Clear and warm						
Existing Acreage: Permitted-1377.75	Disturbed-2	24 Regrad	ed-0 Seeded	- <u>0</u> Bonded- <u>24</u>		
Increased/Decreased: Permitted Dist	turbed Re	egraded	Seeded Bo	nded		
Status: _Exploration/XXX_Active/_]	Inactive/_To	emporary C	Cessation/_Bon	d Forfeiture		
Reclamation (_Phase I/_Phase	II/_Final B	Sond Releas	se/_Liability	Year)		

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.

 a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
- For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		Evaluated	<u>N/A</u>	Comments	NOVENE
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[]	[]	[]	
2.	SIGNS AND MARKERS	īī	Π		\Box
3.	TOPSOIL	Π	Π		\Box
4.	HYDROLOGIC BALANCE:	_			
a.	DIVERSIONS		\Box	\Box	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	$\overline{[X]}$	\Box	[X] [X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X] [X]	\Box	[X]	\Box
d.	WATER MONITORING			Ĺ	\Box
e.	EFFLUENT LIMITATIONS				\Box
5.	EXPLOSIVES	\Box	\Box	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	\Box	$\overline{[X]}$	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		\Box		\Box
8.	NON-COAL WASTE	<u>[X]</u>	\Box	$\overline{[X]}$	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES			\Box	Щ
10.	SLIDES AND OTHER DAMAGE		\Box		Щ
11.	CONTEMPORANEOUS RECLAMATION		\Box	\Box	Щ
12.	BACKFILLING AND GRADING		\square	Щ	Щ
13.	REVEGETATION				ĻĻ
14.	SUBSIDENCE CONTROL	\Box	Ц	Щ	Щ
15.	CESSATION OF OPERATIONS		\Box		Ш
16.	ROADS:				
a.	The state of the s	[X] [X]	Ц	[X] [X]	ĻĻ
	DRAINAGE CONTROLS	<u>[X]</u>	ĻĻ	<u>[X]</u>	ĻĻ
17.	OTHER TRANSPORTATION FACILITIES		ŢŢ	ĻĻ	ĻĻ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	Щ	Щ	ĻĻ	ĻĻ
19.	AVS CHECK (4th Quarter-April, May, June) (date)	لِـلِ	لِــلِ	ļ ļ	닏
20.	AIR QUALITY PERMIT	\sqcup	Ш	ĻĻ	Ļļ
21.	BONDING & INSURANCE		\Box		L

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: <u>07/27/2000</u>

(Comments are Numbered to Correspond with Topics Listed Above)

4b. SEDIMENT PONDS AND IMPOUNDMENTS

- Co-Op has finished cleaning out Sediment Pond A with removal of approximately 7 to 8 feet of sediment. Water from Pond A was decanted and placed into Pond B to allow removal of the sediments. Pond A needs to be recertified.
- Sediment Pond B now contains additional sediment that was transported during the decanting process from Pond A. Accordingly, Pond B needs to be cleaned out to remove these sediments.
- Sediments are placed and air dried alongside the road just north of the truck scales. After drying, the sediment will be placed on the coal pile pad area.

4c. OTHER SEDIMENT CONTROL MEASURES

- Lower silt fence (UD-2) treating undisturbed drainage has been cleaned out.
- Upper Tank Seam ASCA silt fence has collected some sediment that should be removed.

8. NON-COAL WASTE

- The upper garbage dumpster located at the #1 mine Blind seam portal pad was noted as not being full. In addition, there was no garbage lying about the pad area. Last month, Charles had committed to having the garbage cleaned up and to make an additional effort to control the garbage.
- Co-Op has continued removing non-coal waste, old mining machinery, vehicles, etc., from lower facility roadway and pad area. Considerable effort has been made to promptly remove the waste and to keep the area looking clean.
- The maintenance shop area and bone yard had very little garbage on or around the area. The area contains the miscellaneous old mine equipment and supplies.

16a. CONSTRUCTION/MAINTENANCE/SURFACING

- Roads within the lower facility areas have become extremely dry and dusty. Road maintenance includes spraying twice a day with water to help control dust. However, the dry, powdery dust immediately returns once vehicle traffic resumes and the water has dried. Co-Op plans on additional, continued efforts to help control dust. Dust suppression efforts include:
 - 1) add road base 1" size to a depth of 6 inches.
 - 2) apply magnesium chloride to the road surfaces.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 07/27/2000

Date: <u>August 15, 2000</u>

16b. DRAINAGE CONTROLS

- There were several locations of roadside ditches that have been recently cleaned out from the following locations:
 - 1) Lower undisturbed roadside drainage ditches below #1 Mine cleaned out.
 - 2) Upper tank seam road ditches were recently cleaned out.
- The following road drainage culverts need to be cleaned out:
 - 1) Water bar culvert D-8D needs to be cleaned out. The culvert has filled considerably with sediment.
 - 2) Culvert D-1U is partially blocked and needs to be cleaned out.

Copy of this Report:

Mailed to:

James Fulton, OSM

Charles Reynolds, Co-Op Mining Company

Given to:

Daron R. Haddock, DOGM

Inspector's Signature:

Robjert A. Davidson # 45

sm

cc: Price Field Office

O:\015025.BCN\Compliance\2000\P_0727.wpd